

SELLER-SPONSORED VEHICLE TRANSPARENCY PACKET

2018 Toyota Camry SE

Front-wheel drive · 8-speed automatic · 74,216 miles

VIN 4T1B11HK1JU••••••••

Completed portfolio example · Mesa, Arizona · Prepared September 21, 2026

PACKET STATUS

COMPLETED PACKET EXAMPLE

Illustrative sample data only. This vehicle is not being offered for sale.

SAMPLE DATA — NOT A REAL VEHICLE LISTING. This document demonstrates the finished customer format only.

What this is: A seller-sponsored organization of vehicle facts, disclosures, and supporting records. Every material item is labeled by its evidence level.

What this is not: An independent inspection, appraisal, certification, title guarantee, warranty, or recommendation to buy.

Vehicle facts

Item	Evidence	Finding
Vehicle identity	VERIFIED	2018 Toyota Camry SE; demonstration VIN partially redacted in this portfolio sample
Configuration	VERIFIED	Front-wheel drive with 8-speed automatic transmission
Mileage	DOCUMENTED	74,216 miles supported by a timestamped odometer photograph
Asking price	REPORTED	\$16,900 seller asking price; not an independent appraisal
Title / lien	VERIFIED	Redacted title and current lien-status evidence reviewed
Independent inspection	DOCUMENTED	Example independent lift inspection and diagnostic scan dated September 19, 2026

Seller disclosures

Rear bumper cosmetic repair

The rear bumper cover was refinished after a low-speed parking scrape. The seller reports no structural damage; the inspected rear structure showed no visible deformation.

Basis: Repair invoice, photographs, and illustrative inspection report

Small windshield chip

A repaired chip remains visible low on the passenger side and is shown in the condition photographs.

Basis: Dated close-up photograph and repair receipt

Wheel and paint wear

Two wheels have light curb scuffs and the hood has ordinary stone chips consistent with mileage.

Basis: Unedited daylight condition photographs

Tire condition

All four matching tires measured between 6/32 and 7/32 inch during the sample inspection.

Basis: Illustrative inspection measurements and tire photographs

Maintenance and repair summary

Date	Mileage	Event	Why it matters
2023-08-14	48,220	Transmission fluid serviced	Invoice includes fluid specification, mileage, and servicing shop.
2024-05-02	55,811	Four matching tires installed	Invoice and current tread measurements included.
2025-02-18	63,407	Front brake pads and rotors replaced	Itemized repair invoice included.
2026-01-09	69,982	Battery replaced and charging system tested	Receipt and test result included.
2026-09-19	74,205	Independent lift inspection and diagnostic scan	Sample report records tire/brake measurements, scan results, leaks, and photographed condition.

History-report handling: This packet does not reproduce or resell a consumer CARFAX report. Any original report possessed by the seller should be obtained separately and reviewed directly by the buyer.

Evidence index

Evidence item	Status	What is supported
VIN and factory identity	VERIFIED	VIN matched the dashboard, door label, title copy, and vehicle specifications.
Current odometer evidence	DOCUMENTED	Timestamped dashboard photograph shows 74,216 miles.
Title in seller's name	VERIFIED	Redacted title copy matches the seller and VIN.
Lien status	VERIFIED	Current title-view record shows no active lien.
Independent history evidence	DOCUMENTED	Dated history report reviewed; original available directly from the seller.
Maintenance invoices	DOCUMENTED	Oil, transmission-fluid, brake-fluid, tire, battery, and brake invoices indexed by date and mileage.
Known defects disclosed	DOCUMENTED	Cosmetic bumper repair, windshield chip, wheel scuffs, and tire measurements are photographed and described.
Independent pre-purchase inspection	DOCUMENTED	Dated lift inspection and diagnostic scan supplied with measurements and photographs.
VIN-specific recall status	VERIFIED	Dated manufacturer campaign printout supplied.
Current emissions evidence	DOCUMENTED	Current Arizona emissions result and complete readiness-monitor scan supplied.
Detailed condition photographs	DOCUMENTED	Exterior, interior, engine bay, tires, underside, VIN labels, and every disclosed flaw photographed in daylight.
Keys and remotes	VERIFIED	Two working factory smart keys photographed and tested.
Buyer-selected PPI permission	DOCUMENTED	Seller agrees in writing to an additional inspection chosen and paid for by the buyer.

Independent buyer verification

- Match the complete VIN on the dashboard, door label, title, and supporting records.
- Verify ownership and lien status directly with the applicable motor-vehicle authority before payment.
- Obtain and review an independent vehicle-history report directly from its authorized provider.
- Choose and pay the inspection shop yourself if you want an additional pre-purchase inspection.
- Treat this packet as organized disclosure—not a warranty, certification, or recommendation to buy.

Buyers should verify before paying. Confirm the VIN, title ownership, lien status, odometer, recall status, history, and mechanical condition independently. Choose and pay the inspection shop yourself.

Seller transparency statement

A seller-sponsored transparency packet is available with identity, mileage, title/lien evidence, known-condition disclosures, maintenance invoices, a recent independent inspection, and recall/emissions records. Buyers are encouraged to verify every material fact and arrange their own pre-purchase inspection.

Sources & limitations

- Illustrative redacted title and lien-status record — sample only
- Illustrative maintenance invoice index — sample only
- Illustrative independent inspection — sample only
- Illustrative campaign and emissions records — sample only

SAMPLE DATA — This completed portfolio example does not describe a vehicle offered for sale. A real seller-sponsored packet organizes supplied facts and supporting records but is not an inspection, appraisal, title guarantee, certification, warranty, or recommendation to buy. Buyers remain responsible for independent verification.